	Туре	#	Hits	Search Text	DBs	Time Stamp	Comments
1					GPUB;		
Н	BRS	F2	ω	"2001/017775" "090957"	DERWENT:	2005/11/30	
					IBM_TDB		
В	BRS	L4	27	reinert.in.	US-PGPUB	2005/11/30 13:36	
				(road with (marker marking)) and (light lighting reflector	ď		
ω	BRS	<u>F</u>	, L	ng) and (electrical nductor ng)) and (cable	JPO; DERWENT; IBM_TDB	14:54	
44	BRS	9	10	"1011959".pn. "1010491".pn.	EPO; DERWENT; IBM_TDB	2005/11/30 14:13	
И	BRS	L7	12	"9900680"	EPO; DERWENT; IBM_TDB	2005/11/30 14:42	
თ	BRS	L9	244	((roadway road) and (marker marking)) and (LED illuminat\$ bulb light lighting reflector reflecting) and (electrical with (conductor conducting)) and (cable)	B; EPO;	2005/11/30 14:57	

7	
BRS	Туре
L10	Т #
34	Hits
((roadway road) with (marker marking)) and (LED illuminat\$ bulb light lighting reflector reflecting) and (electrical with (conductor conducting)) and (cable)	Search Text
US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	DBs
2005/11/30 14:57	Time Stamp Comments
	Comments

7	
	Error
	Error Definition
·	Err

	Туре	Hits	Search Text	DBs	Time Stamp
Р	BRS	6	"404"/\$.ccls. and (road with (marker marking)) and (light US-PGPUB; Ulighting reflector reflecting) USOCR; EPO; and (electrical with (conductor conducting))	SPAT; JPO; M_TDB	2005/11/30 13:37
8	BRS	30	"2001017775" "1006641" "90957" US-PGPUB; EPO;	DB	2005/11/30 13:35